To: Turner, Alison[alison.turner@mountainview.gov]

Cc: Lee, Alana[lee.alana@epa.gov]; Sandahl, Carrie[Carrie.Sandahl@mountainview.gov]

From: Anderson, Eric - Fire Sent: Wed 4/30/2014 10:31:09 PM

Subject: RE: Follow-up EPA data request to City of Mtn View

Federal Categorical Facilities.pdf

Final round, which are 2 permits issued to Federal categorical facilities (Metal Finishers):

• 🗆 🗆 🗆 🗆 Applied Nanostructures

Caliper is closed and no longer operating.

All of the permits provided represent current or most recent operations and does not reflect historic facility operations in the area.

Please call if you have questions.

Eric

From: Turner, Alison

Sent: Wednesday, April 30, 2014 1:10 PM

To: Anderson, Eric - Fire

Subject: FW: Follow-up EPA data request to City of Mtn View

Can you help with the first item or direct me to where it might be?

From: Lee, Alana [mailto:lee.alana@epa.gov]
Sent: Wednesday, April 30, 2014 7:00 AM

To: Turner, Alison

Cc: Plambaeck, Scott; Fuller, Michael

Subject: Follow-up EPA data request to City of Mtn View
Hi Alison,
EPA has a few follow-up items we need. Please provide
•□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
•□□□□□□□ Planned / priority replacement schedule of the Fairchild Drive sewer trunk lines, National Avenue, Ellis Street, N Whisman Road
•□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□
- Abandoned line at the former GTE Facility (100 Ferguson Dr)
o The GIS data indicates that there is an abandoned line that extends approx. 340 feet. When was this line abandoned? Why was it abandoned? Was it abandoned in place?). City: <i>Please provide a vicinity map</i> EPA: See attached map (20140408_100Ferguson)
- Moffett Blvd and Leong Sewer lines
o Did the Moffett Blvd and Leong sewer lines ever connect? For example, was there ever a line connecting manholes F5-067 and F5-073?
City: Don't understand question? I don't see F5-67 Look at F5 system map. Moffett Blvd was renamed Leong when the freeway connector was constructed. The freeway connector was named Moffett Boulevard and the State typically doesn't allow for longitudinally placed utilities
O EPA: The attached map highlights the F5-067 and F5-073 manholes (20121017_F5_Sanitary Sewer Map_[967]_Markup). The 1960 as -build posted to Dropbox (Record drawing 2660) seems to show that the sewer lines did not connect. However, please

confirm.

Thanks for all your help in providing all the information. Please let me know if you have any questions.

Alana Lee

EPA Project Manager

Superfund Division

415.972.3141

Lee.Alana@epa.gov